ie:

Invoice



Sold To:

Renergy, Inc. PO Box 249 Delaware, OH 43015 United States
 Invoice Number:
 0195235-IN

 Invoice Date:
 11/8/2021

 Invoice Due Date:
 12/8/2021

 Order Number:
 0163504

 Order Date
 6/2/2021

 Salesperson:
 Daniel Sensenig

Customer Number: RINEME01

Ship To:

Emerald Bio Energy 2277 County Rd. 156 Cardington, OH 43315United States

Confirm To: Rich Oberfield

Customer P.O Rebuild	. Sr	nip VIA		F.O.B. Ephrata, PA	Terms Net 30 Days		
Item Code	Ur	nit	Ordered	Shipped	Back Ordered	Price	Amount
/PSVC	E.A	4	1.00	0.00	1.00	0.0000	0.00
	Major Overhaul or	n SFGLD	480				
/PDOWNPAYM	IENT EA	4	1.00	1.00	0.00	Not Responsive	Not Responsive
	Downpayment PA	١					
/PDOWNPAYM	IENT EA	4	1.00-	0.00	0.00	Not Responsive	0.00
	Downpayment PA	١					
/PROGRESSP	AYMENT EA	4	1.00	1.00	0.00	Not Responsive	Not Responsive
	Progress Paymen	ıt					
/PROGRESSP	AYMENT EA	4	1.00-	0.00	0.00	Not Responsive	0.00
	Progress Paymen	nt					
714-REM-1910	910 6 EA	4	16.00	0.00	16.00	Not Responsive	0.00
	SG2211 SG6972	8 SG320	00 SG73141 SG1348	SG70369 SG2209 S	180,240,360,&480) with ex G76915 SG76920 SG769	• ,	ot Included)
103502	SG/0615 SG221 EA)65 SG67505 SG761 17.00	22 SG966 0.00	17.00	Not Responsive	0.00
100002	Head Gasket Kit,	•		0.00	17.00		0.00
103244	FA		11.00	0.00	11.00	Not Responsive	0.00
103244	Stud, Anti-Knock			0.00	11.00		0.00
103406	EA	•	4.00	0.00	4.00	Not Responsive	0.00
	Nut, Head Stud, C	•					
103486	EA		11.00	0.00	11.00	Not Responsive	0.00
		•	0) includes ring kit				
103486	EA	A	5.00	0.00	5.00	Not Responsive	0.00
	Piston Kit,11.8 - 1	, (180-48	0) includes ring kit				
/PFREIGHT	EA Freight 527544624555	\	1.00	0.00	1.00	Not Responsive	0.00



Sold To:

Renergy, Inc. PO Box 249 Delaware, OH 43015 United States
 Invoice Number:
 0195235-IN

 Invoice Date:
 11/8/2021

 Invoice Due Date:
 12/8/2021

 Order Number:
 0163504

 Order Date
 6/2/2021

 Salesperson:
 Daniel Sensenig

 Customer Number:
 RINEME01

Ship To:

Emerald Bio Energy 2277 County Rd. 156 Cardington, OH 43315United States

Confirm To: Rich Oberfield

Customer P.O. Rebuild	Ship VIA		. O.B. phrata, PA	Terms Net 30 Days		
Item Code	Unit	Ordered	Shipped	Back Ordered	Price	Amount
102623	EA Liner Assy, SFGLD(180-480) Had 16, 7left	16.00	0.00	16.00	Not Responsive	0.00
103134	EA Bearing, Conrod (180 - 560)	16.00	0.00	16.00	Not Responsive	0.00
103136	EA Bearing, Main, V Engine	9.00	0.00	9.00	Not Responsive	0.00
103247	EA Washer, Crankshaft Thrust	2.00	0.00	2.00	Not Responsive	0.00
103257	EA Seal, Rear Main (180-560)	1.00	0.00	1.00	Not Responsive	0.00
102679	EA Gasket Rear Main Seal	1.00	0.00	1.00	Not Responsive	0.00
103256	EA Seal, Front Main (180-560)	1.00	0.00	1.00	Not Responsive	0.00
102633	EA ConRod, Complete 360/480	16.00	0.00	16.00	Not Responsive	0.00
102632	EA Turbo,TD13 , 240/480 @ 180	2.00 0RPM	0.00	2.00	Not Responsive	0.00
103510	EA Blanket, Turbo Elbow TD09/T	2.00	0.00	2.00	Not Responsive	0.00
103513	EA Blanket, Turbo TD13	2.00	0.00	2.00	Not Responsive	0.00
103512	EA Blanket, Turbo RiserTD09/TD	2.00	0.00	2.00	Not Responsive	0.00
102703	EA Gasket, Turbo Mtg, 240/480/5	2.00	0.00	2.00	Not Responsiv	0.00

3

Invoice



Sold To:

Renergy, Inc. PO Box 249 Delaware, OH 43015 United States

Invoice Number: 0195235-IN Invoice Date: 11/8/2021 Invoice Due Date: 12/8/2021 Order Number: 0163504 **Order Date** 6/2/2021 Salesperson: Daniel Sensenig Customer Number: RINEME01

Ship To:

Emerald Bio Energy 2277 County Rd. 156 Cardington, OH 43315United States

Confirm To: Rich Oberfield

Customer P.O. Rebuild	Ship VIA		F.O.B. Ephrata, PA	Terms Net 30 Days				
Item Code	Unit	Ordered	Shipped	Back Ordered	Price	Amount		
103254	EA	4.00	0.00	4.00	Not Responsiv	0.00		
	Gasket,Turbo Drain							
714-1545029-S	EA	1.00	0.00	1.00	Not Responsiv	0.00		
	Gasket, Turbo Discharge	Drain Pipe (HX52)						
714-12.45.003	EA	2.00	0.00	2.00	Not Responsiv	0.00		
	Gasket Turbo Oil Supply							
103278	EA	2.00	0.00	2.00	Not Responsiv	0.00		
	O-ring, 78 Viton							
103323	EA	4.00	0.00	4.00	Not Responsive	0.00		
	O-Ring, Viton, Turbo Outlet							
	Had 4, 7 Left							
103335	EA	2.00	0.00	2.00	Not Responsive	0.00		
	O-ring, viton							
103267	EA	2.00	0.00	2.00	Not Responsiv	0.00		
	Bolt, M10 x 35							
103268	EA	6.00	0.00	6.00	Not Responsiv	0.00		
	Bolt, M10 x 45							
103182	EA	2.00	0.00	2.00	Not Responsive	0.00		
	Clamp, turbo to exhaust e	lbow (TD13)						
103070	EA	16.00	0.00	16.00	Not Responsive	0.00		
	Thermocouple, 4 in Probe	20 ft Leads Ending In	Pigtails Type K 180-56	0				
103118	EA	16.00	0.00	16.00	Not Responsive	0.00		
	Fitting, Compression, 1/4	in mnpt 316 SS						
102687	EA	2.00	0.00	2.00	Not Responsiv	0.00		
	Gasket, Intake Manifold		3.00			0.00		
	Had 2							
102704	EA	16.00	0.00	16.00	Not Responsive	0.00		
	Gasket, Side Cover, V Eng		3.00			0.00		
	222, 0140 00101, V EIN	, .						



Sold To:

Renergy, Inc. PO Box 249 Delaware, OH 43015 United States

Invoice Number: 0195235-IN Invoice Date: 11/8/2021 Invoice Due Date: 12/8/2021 Order Number: 0163504 **Order Date** 6/2/2021 Salesperson: Daniel Sensenig Customer Number: RINEME01

Ship To:

Emerald Bio Energy 2277 County Rd. 156 Cardington, OH 43315United States

Confirm To: Rich Oberfield

Customer P.O. Rebuild	Ship VIA		O.B. phrata, PA	Terms Net 30 Days		
Item Code	Unit	Ordered	Shipped	Back Ordered	Price	Amount
784-1792	EA	3.00	0.00	3.00	Not Responsive	0.00
	Oil Filter					
105836	EA	1.00	0.00	1.00	Not Responsive	0.00
	Oil Shell Mysella S5 N 40	W Long life low ash0.48	TBN4.5 55 Gal. Drum			
103188	EA	16.00	0.00	16.00	Not Responsive	0.00
	O-Ring, Cam Inspection	Cover				
103251	EA	17.00	0.00	17.00	Not Responsive	0.00
	Bushing, Camshaft Cente	er 360-560				
103232	EA	1.00	0.00	1.00	Not Responsive	0.00
	Bushing, Camshaft Front	360-560				
103744	EA	1.00	0.00	1.00	Not Responsive	0.00
	Reman Camshaft Left 48 Core Charge \$4,500 not i		stamp is 16.15.508			
103768	EA	1.00	0.00	1.00	Not Responsive	0.00
	Camshaft, Reman Right 4 Core Charge \$4,300 not i	480 - 560 SFGLD Prefini included	sh stamp is 16.15.507			
714-16.10.135-	A EA	2.00	0.00	2.00	Not Responsiv	0.00
	Camshaft Adjusting Shim	0.002in				
103492	EA	10.00	0.00	10.00	Not Responsive	0.00
	Cam Follower, New Style	;			<u></u>	
	Had 17 - check					
103243	EA	22.00	0.00	22.00	Not Responsive	0.00
	Roller, Cam Follower (36	0-560) For Cam Followe	r 16.15.A60			
	check	•				
714-16.15.415	EA	22.00	0.00	22.00	Not Responsive	0.00
	Shaft, Cam Follower (360),480)				
	check	. ,				
784-REM16.26.	370 EA	1.00	0.00	1.00	Not Responsive	0.00
704-11LW110.20.	.570 EA	1.00	0.00	1.00		0.0



Sold To:

Renergy, Inc. PO Box 249 Delaware, OH 43015 United States

Invoice Number: 0195235-IN Invoice Date: 11/8/2021 Invoice Due Date: 12/8/2021 Order Number: 0163504 **Order Date** 6/2/2021 Salesperson: Daniel Sensenig Customer Number: RINEME01

Ship To:

Emerald Bio Energy 2277 County Rd. 156

Cardington, OH 43315United States

Confirm To: Rich Oberfield

Customer P.O. Rebuild	Ship VIA		O.B. ohrata, PA	Terms Net 30 Days		
Item Code	Unit	Ordered	Shipped	Back Ordered	Price	Amount
	Rebuilt Oil Pump for 480, 5 Core Charge \$1,800 additi					
784-REM16.27.		1.00	0.00	1.00	Not Responsive	0.00
	Rebuilt Safty Valve, Oil Pre Core Charge \$375 addition					
103518	EA	1.00	0.00	1.00	Not Responsive	0.00
	Oil Cooler Core Bundle, TF	PE3 (360-480-560)				
103191	EA	2.00	0.00	2.00	Not Responsive	0.00
	O-ring, TPE3 Oil Cooler Co	ore				
102400	EA	1.00	0.00	1.00	Not Responsive	0.00
	Core, Aftercooler New 360	-560, single circuit				
103736	EA	6.00	0.00	6.00	Not Responsive	0.00
	Pad Isolator, rated 7,000lb	s 4"x8"x1"H. with 1/2-1	3 threaded stud. 1-1/2	?"lona		
103738	EA	12.00	0.00	12.00	Not Responsive	0.00
	Rubber Isolator, 2100#					
106882	EA	2.00	0.00	2.00	Not Responsive	0.00
	Flex, Exhaust, 6.63in ID x 9 T321 STAINLESS STEEL END EXPANDED TO SLIF	2-PLY BELLOWS ӁITI	H 1" LONG TANGEN	TS EACH		
103972	EA	1.00	0.00	1.00	Not Responsive	0.00
	Filter, Crankcase, 800-160	0 HP				
714-16.15.016	EA	1.00	0.00	1.00	Not Responsive	0.00
	Ring Gear 360-560					
103381	EA	1.00	0.00	1.00	Not Responsiv	0.00
	Pin, Head line up					
/PLC4	LABR	1.00	0.00	1.00	Not Responsive	0.00
	Machine rear main seal ho	lder				
116579	EA	3.00	0.00	3.00	Not Responsiv	0.00
	Starter Mounting Bolt, Gua	scor				
	2 2 2 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3					

Invoice



Invoice Number: 0195235-IN Invoice Date: 11/8/2021 Invoice Due Date: 12/8/2021 Order Number: 0163504 **Order Date** 6/2/2021

Salesperson: Daniel Sensenig Customer Number: RINEME01

Ship To:

Emerald Bio Energy 2277 County Rd. 156 Cardington, OH 43315United States

Sold To:

Renergy, Inc. PO Box 249 Delaware, OH 43015 United States

Confirm To: Rich Oberfield

Customer P.O. Rebuild	Ship VIA		O.B. ohrata, PA	Terms Net 30 Days		
Item Code	Unit	Ordered	Shipped	Back Ordered	Price	Amount
772-16.77.470	EA	1.00	0.00	1.00	Not Responsive	0.00
	Repair Kit Main Water Pump					
103331	EA	1.00	0.00	1.00	Not Responsive	0.00
	O-Ring, Viton, Oil Pump Such	tion Adapter & Oil Dis	stributor & Tube On Oil	Filter Base (360, 480)	O-ring, Aftercooler to	intake elbo (180, 240)
103300	EA	2.00	0.00	2.00	Not Responsiv	0.00
	O-Ring, Oil Pump Relief Tube	e (360, 480)				
102678	EA	1.00	0.00	1.00	Not Responsive	0.00
	Gasket Oil Thermostat Cover	r (360-560)				
103231	EA	12.00	0.00	12.00	Not Responsive	0.00
	Bolt, Allen Head Socket Cap,	M18-2.5x120mm, G	r12.9, Bolts Hub To Cr	ank		
714-16.15.082	EA	10.00	0.00	10.00	Not Responsive	0.00
	Bolt, fly wheel to flywheel add	apter (M16-2.0x70MN	/ / 12.9 Grd)			
714-70.12.358	EA	24.00	0.00	24.00	Not Responsiv	0.00
	Exh Manifold Section Bolt 12	mmX40mm 12.9 Soc	ket Head Allen			
109231	EA	5.00	0.00	5.00	Not Responsive	0.00
	Gasket, between water coole	d Manifold on SFGLI)			
103301	EA	2.00	0.00	2.00	Not Responsiv	0.00
	Oring, On Oil Cooler Flange ((180 240 360 & 480)	Small			
103309	EA	2.00	0.00	2.00	Not Responsiv	0.00
	O-Ring, Intake manifold & co	oling pipe to aftercoo	ler			
714-19.40.050	EA	1.00	0.00	1.00	Not Responsive	0.00
	Exhaust Manifold-cast#1940	003				
116646	EA	4.00	0.00	4.00	Not Responsive	0.00
	Thermostat, Aftercooler (30°C	C / 86°F)				
103372	EA	11.00	0.00	11.00	Not Responsive	0.00
	Washer, Thermostat Housing	1				
103174	FA	11.00	0.00	11.00	Not Responsive	0.00
	Ring, Thermostat Seal (480)					
	3: ()					

Invoice



Sold To:

Renergy, Inc. PO Box 249 Delaware, OH 43015 United States

Invoice Number: 0195235-IN Invoice Date: 11/8/2021 Invoice Due Date: 12/8/2021 Order Number: 0163504 **Order Date** 6/2/2021 Salesperson: Daniel Sensenig Customer Number: RINEME01

Ship To:

Emerald Bio Energy 2277 County Rd. 156 Cardington, OH 43315United States

Confirm To: Rich Oberfield

Customer P.O. Rebuild	Ship VIA		O.B. ohrata, PA	Terms Net 30 Days		
Item Code	Unit	Ordered	Shipped	Back Ordered	Price	Amount
103324	EA	3.00	0.00	3.00	Not Responsiv	0.00
	O-ring					
103186	EA	1.00	0.00	1.00	Not Responsive	0.00
	O-Ring					
102694	EA	1.00	0.00	1.00	Not Responsive	0.00
	Gasket, Water Thermostat	, ,				
103374	EA	1.00	0.00	1.00	Not Responsiv	0.00
	Circlip, for Thermostat					
102671	EA	4.00	0.00	4.00	Not Responsive	0.00
	Gasket, Turbo Riser To Ex					
102666	EA	4.00	0.00	4.00	Not Responsiv	0.00
	Gasket, Exhaust Man Wat					
103240	EA	4.00	0.00	4.00	Not Responsive	0.00
	Pushrod, SFGLD180-480					
772-31.20.161	EA	1.00	0.00	1.00	Not Responsive	0.00
	Coupling Water Pump					
100422	EA	2.00	0.00	2.00	Not Responsive	0.00
	Gasket Metric 3.25" ID 8 b	olt Flange water outlet	on Guascor engine			
102658	EA	2.00	0.00	2.00	Not Responsive	0.00
	Gasket Intercooler (360-56					
102670	EA	2.00	0.00	2.00	Not Responsiv	0.00
	Gasket, Square top afterco					
102697	EA	4.00	0.00	4.00	Not Responsi	0.00
	Gasket - water pipe flange					
103153	EA	1.00	0.00	1.00	Not Responsive	0.00
	O-Ring, Aftercooler Air Inle					
103297	EA	2.00	0.00	2.00	Not Responsiv	0.00
	O-Ring					



Sold To:

Renergy, Inc. PO Box 249 Delaware, OH 43015 United States

Invoice Number: 0195235-IN Invoice Date: 11/8/2021 Invoice Due Date: 12/8/2021 Order Number: 0163504 **Order Date** 6/2/2021 Salesperson: Daniel Sensenig

Customer Number: RINEME01

Ship To:

Emerald Bio Energy 2277 County Rd. 156 Cardington, OH 43315United States

Confirm To: Rich Oberfield

Customer P.O. Rebuild	Ship VIA		. O.B. phrata, PA	Terms Net 30 Days		
Item Code	Unit	Ordered	Shipped	Back Ordered	Price	Amount
714-305794C	EA	16.00	0.00	16.00	Not Responsiv	0.00
	Gasket, Exhaust Manifold	to Water Connection (Elbo to Head-Same as	19.20.055) (180, 240, 36	0, & 480)	
714-304324C	EA	16.00	0.00	16.00	Not Responsiv	0.00
	Gasket, Water Connection					
103285	EA	16.00	0.00	16.00	Not Responsiv	0.00
	O-ring, for Exh. Water Elb	ow				
101897	EA	2.00	0.00	2.00	Not Responsiv	0.00
	Oring for 8235-195 throttle 5.609" ID x 5.887" OD	e for HGM 560, Viton				
103177	EA	7.00	0.00	7.00	Not Responsive	0.00
	ThERMOSTAT, X2.409.7	5.100/75º88				
774-WL-1250-3	8 EA	2.00	0.00	2.00	Not Responsiv	0.00
	Loom Clamp,1-1/4", 3/8 M	lountin				
103333	EA	1.00	0.00	1.00	Not Responsiv	0.00
	O-Ring					
103326	EA	1.00	0.00	1.00	Not Responsiv	0.00
	O-Ring, For Flange Side (Of P/N 16.20.454 Jacke	t Water Inlet			
104038	EA	4.00	0.00	4.00	Not Responsiv	0.00
	Isolator, 8lb, 5/16 in Vibrat	tion				
714-76.82.017	EA	4.00	0.00	4.00	Not Responsiv	0.00
	Elastic Suspension					
714-76.82.013	EA	20.00	0.00	20.00	Not Responsiv	0.00
	Elastic Element w/ nuts &	washers				
770-060-008666		2.00	0.00	2.00	Not Responsive	0.00
	Cover Danfoss single con					
780-TB-375	EA	6.00	0.00	6.00	Not Responsiv	0.00
	T-Bolt Clamp, 3-3/4"					



Sold To:

Renergy, Inc. PO Box 249 Delaware, OH 43015 United States Invoice Number: 0195235-IN
Invoice Date: 11/8/2021
Invoice Due Date: 12/8/2021
Order Number: 0163504
Order Date 6/2/2021
Salesperson: Daniel Sensenig

Ship To:

Emerald Bio Energy 2277 County Rd. 156

Cardington, OH 43315United States

Customer Number: RINEME01

Confirm To: Rich Oberfield

Customer P.O. Rebuild	Ship VIA		. O.B. phrata, PA	Terms Net 30 Days		
Item Code	Unit	Ordered	Shipped	Back Ordered	Price	Amount
778-099-408	EA	1.00	0.00	1.00	Not Responsiv	0.00
	Gasket, DN65 (2-1/2")					
103189	EA	2.00	0.00	2.00	Not Responsive	0.00
	O-Ring, For Intake Pipe fr	om Mixer to Turbo.				
778-030-221	EA	1.00	0.00	1.00	Not Responsiv	0.00
	Gasket, DN50 (2"")					
116728	EA	1.00	0.00	1.00	Not Responsive	0.00
	Bearing, Auxiliary Water F	ump Drive (SFGLD 480	0)			
116727	EA	1.00	0.00	1.00	Not Responsive	0.00
	Shaft Seal, Auxiliary Water	er Pump (SFGLD 480)				
101779	EA	1.00	0.00	1.00	Not Responsive	0.00
	Bearing, Rubber Seal Bot	h Sides				
103104	EA	1.00	0.00	1.00	Not Responsive	0.00
	Transducer, Pressure, 0-5	0 PSI, Analogue, Abso	lute, 30VDC, 4 to 20	mA, 1/4in NPT, mini DIN co	nnection, OMEGA	
770-1689-1291	EA	1.00	0.00	1.00	Not Responsive	0.00
	Sensor, position feedback Negative Slope	for ProAct II				
/PA PARTS	EA	10.00	0.00	10.00	Not Responsiv	0.00
	56315K53 - Hose for Petr	oleum, Low-Pressure, F	Flexible, 2" ID, 2-9/16	6" OD		
	to Weston N.					
103052	EA	1.00	0.00	1.00	Not Responsive	0.00
	Temp Sensor, -32°F - 390	9°F, 1.3" Extension , 1/4	l" BSPP Conn. 4-20i	mA, 10-32V		
106967	EA	1.00	0.00	1.00	Not Responsive	0.00
	Temperature Transmiter,	XTP25N-100-0300F			<u> </u>	

Dro Conce temperature transmitter

ProSense temperature transmitter,

integral Pt100 RTD, 0 to 300 deg F, 6mm probe diameter, 100mm insertion length, 1/4in MNPT process connection, 4-20 mA analog output,

4-pin M12 quick-disconnect.



Sold To:

Renergy, Inc. PO Box 249 Delaware, OH 43015 United States
 Invoice Number:
 0195235-IN

 Invoice Date:
 11/8/2021

 Invoice Due Date:
 12/8/2021

 Order Number:
 0163504

 Order Date
 6/2/2021

 Salesperson:
 Daniel Sensenig

 Customer Number:
 RINEME01

Ship To:

Emerald Bio Energy 2277 County Rd. 156

Cardington, OH 43315United States

Confirm To: Rich Oberfield

Customer P.O. Rebuild	St	nip VIA	F.O.B Ephra	ta, PA	Terms Net 30 Days		
Item Code	Ur	nit C	rdered	Shipped	Back Ordered	Price	Amount
103069	E.A	4	1.00	0.00	1.00	Not Responsive	0.00
	Plug, R-angle 4pi	n ProSense Te	emp. Transmitter				
102870	EA	A	1.00	0.00	1.00	Not Responsive	0.00
	Starter, Reman Di	rect drive Leed	ce Neville, for Guasco	r 360-480-560			
103322	EA	A	1.00	0.00	1.00	Not Responsiv	0.00
	O-Ring, Oil T/Stat	t Housing					
722-A-66377-45	5 EA	A	1.00	0.00	1.00	Not Responsive	0.00
	Capacitor 7.5uf 3	70vac (for DVF	Regulators)				
/PA PARTS	EA	A	1.00	0.00	1.00	Not Responsive	0.00
	Used DVR2000E						
	Check Price						
/PSTZ2DCOMM	MERCIAL EA	A	2.00	0.00	2.00	Not Responsive	0.00
	Service Trip Zone	-					
	Generator to & fro	m Burkholder					
/PA PARTS	EA	•	3.00	0.00	3.00	Not Responsiv	0.00
	25109 - HELICO	IL; M10 X 1.5N					
/PEA340	EA	A	1.00	0.00	1.00	Not Responsive	0.00
	Emission Analyze	er service/day					
/MISC	EA	A	1.00	0.00	1.00	Not Responsive	0.00
	Rebuild parts for	JW and I/C pu					
/PA PARTS	EA	4	1.00	0.00	1.00	Not Responsive	0.00
	Shop Supplies - C	Consumable Ite					
/PLC1	LA	\BR	1.00	0.00	1.00	Not Responsive	0.00
	Labor, Rebuild en	igine and gene					
/PLC4	LA	\BR	1.00	0.00	1.00	Not Responsive	0.00
	Refurb generator Clean, Revarnish		t the windings Replace	e Bearings & Flex I	Drive coupling		



Sold To:

Renergy, Inc. PO Box 249 Delaware, OH 43015 United States

Invoice Number: 0195235-IN **Invoice Date:** 11/8/2021 Invoice Due Date: 12/8/2021 Order Number: 0163504 **Order Date** 6/2/2021

Page:

11

Salesperson: Daniel Sensenig Customer Number: RINEME01

Ship To:

Emerald Bio Energy 2277 County Rd. 156

Cardington, OH 43315United States

Confirm To: Rich Oberfield

Customer P.O. Rebuild		Ship VIA		O.B. ohrata, PA	Terms Net 30 Days		
Item Code		Unit	Ordered	Shipped	Back Ordered	Price	Amount
/MISC		EA	1.00	0.00	1.00	Not Responsive	0.00
	Load Test on I	NG					
/PFREIGHT		EA	1.00	0.00	1.00	Not Responsive	0.00
	Freight - Subje	ect to Change					
/PA PARTS		EA	1.00	0.00	1.00	Not Responsive	0.00
	Misc. Parts, se	eals, gaskets					
/PLC1		LABR	1.00	0.00	1.00	Not Responsive	0.00
	Labor Startup	and commiss	ion Engine				
/PSTZ13DCOMN	MERCIAL	EA	1.00	0.00	1.00	Not Responsive	0.00
	Service Trip Z	one 13 COM-	Day				

Please Remit Payment To:

Martin Energy Group Services, LLC PO BOX 729

Tipton, MO 65081

166,950.00 Net Invoice: Less Discount: 0.00 0.00 Freight: 0.00 Sales Tax: 166,950.00 Invoice Total: (USD)

Canadian Dollars Total

Sale in accordance with Martin Energy Group Services, LLC Conditions of Sale. 1.5% per month Finance Charges may apply on overdue invoices.

PAYMENT TERMS: 50% down, 40% @ completion of rebuild, balance Net 30